

# **Inspection Report**

## Mr. John Sample

## **Property Address:**

4321 New Home Road Doylestown PA 18901



Maurer Inspections, LLC

Steve Maurer 3633 Buttonwood Drive Doylestown, PA 18902 267-884-4047 NJ Lic#24G100097300



4321 New Home Road Page 1 of 26

## **Table of Contents**

Cover Page

**Table of Contents** 

Intro Page

**General Summary** 

- 1 Roofing
- 2 Exterior
- 3 Interiors
- **4 Structural Components**
- 5 Plumbing System
- 6 Electrical System
- 7 Heating
- 8 Central Air Conditioning
- 9 Attic & Venting
- 10 Basement
- 11 Built-In Kitchen Appliances
- 12 Garage

**Back Page** 

4321 New Home Road Page 2 of 26

<b>Date</b> : 5/4/2009	<b>Time:</b> 01:00 PM	<b>Report ID</b> : 090504
Property: 4321 New Home Road Doylestown PA 18901	<b>Customer:</b> Mr. John Sample	Real Estate Professional: Your Agent ABC Realty Agency

#### **Comment Key or Definitions**

The following definitions of comment descriptions represent this inspection report. All comments should be considered before purchasing this home. Recommendations to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the home.

Inspected - Appears Functional: The item, component, or unit was visually observed and the item appeared to be functioning as intended, allowing for normal wear and tear.

Material Defects: The item has a significant adverse impact on the value of the property of that involves and unreasonable risk to people on the property.

**Recommendations:** The item, component or unit was visually observed, and is not functioning as intended or needs further inspection by a qualified specialist. Items, components or units that can be repaired to satisfactory condition may not need replacement.

Service Needed: The item, component, or unit is functioning, but a service check-up is recommended to optimize performance.

Limited Inspection: The item, component, or unit was not fully inspected, and some form of limitation is preventing a complete inspection of the item/area.

Not Inspected: The item, component, or unit was not inspected, and no representations of whether or not it was functioning as intended are made.

All recommendations for repair, replacement, or further analysis should be performed by a qualified professional.

Style: Age Of Home: **Client Is Present:** Under 10 Years Yes

Contemporary, Colonial

Radon Test: Water Test: Weather: No No Clear

Temperature: Rain in last 3 days:

Over 65 Yes

4321 New Home Road Page 3 of 26

## **General Summary**



Maurer Inspections, LLC

3633 Buttonwood Drive Doylestown, PA 18902 267-884-4047 NJ Lic#24G100097300

#### Customer

Mr. John Sample

#### **Address**

4321 New Home Road Doylestown PA 18901

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling**; or **warrants further investigation by a specialist**, or **requires subsequent observation**. This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

## 6. Electrical System

#### 6.2 MAIN OVERCURRENT PROTECTION, MAIN DISTRIBUTION PANELS

#### Repair or Replace

- (1) The door bell transformer laying within the electric cabinet should be located outside the cabinet to reduce the possibility of an electric fire.
- (2) The uppermost AFCI breaker with a broken test button should be replaced so an AFCI test of that circuit can be performed to reduce the risk of an electric fire.
- 6.4 BRANCH CIRCUIT CONDUCTORS, OVERCURRENT DEVICES AND COMPATIBILITY OF THEIR AMPERAGE AND VOLTAGE

#### Repair or Replace

The romex wire laying within the breaker panel and the other end of it (which may be in the furnace room) should be terminated properly to prevent the possibility of an electric shock.

4321 New Home Road Page 4 of 26

## 7. Heating

#### 7.7 SOLID FUEL HEATING DEVICES (Fireplaces, Woodstove)

#### Repair or Replace

The deteriorated fire brick plate in the back wall of the fireplace should be replaced to prevent a house fire from the fireplace.

Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; or Predict future condition, including but not limited to failure of components.

Prepared Using HomeGauge http://www.homegauge.com SHGI (c) 2000-2008: Licensed To Maurer Inspections, LLC

4321 New Home Road Page 5 of 26

## 1. Roofing

The home inspector shall inspect: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to walk on the roof or inspect: Antennae; Interiors of flues or chimneys that are not readily accessible; Other installed accessories including but not limited to solar systems, and lightning arrestors.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
1.0	ROOF COVERINGS Roof Covering: Architectural Shingles
	Viewed roof covering from: Binoculars
X	FLASHINGS Flashings: Aluminum
X	ROOF DRAINAGE SYSTEMS
X	CHIMNEYS Sky Light(s): None
X       1.4	ROOF PENETRATIONS Penetrations: Plumbing Vent

#### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 6 of 26

#### 2. Exterior

The home inspector shall observe: Wall cladding, flashings, and trim; Entryway doors and a representative number of windows; Garage door operators; Decks, balconies, stoops, steps, areaways, porches and applicable railings; Eaves, soffits, and fascias; and Vegetation, grading, drainage, driveways, patios, walkways, and retaining walls with respect to their effect on the condition of the building. The home inspector shall: Describe wall cladding materials; Operate all entryway doors and a representative number of windows; Operate garage doors manually or by using permanently installed controls for any garage door operator; Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; and Probe exterior wood components where deterioration is suspected. The home inspector is not required to observe: Storm windows, storm doors, screening, shutters, awnings, and similar seasonal accessories; Fences; Presence of safety glazing in doors and windows; Garage door operator remote control transmitters; Geological conditions; Soil conditions; Recreational facilities (including spas, saunas, steam baths, swimming pools, tennis courts, playground equipment, and other exercise, entertainment, or athletic facilities); Detached buildings or structures; or Presence or condition of buried fuel storage tanks. The home inspector is not required to: Move personal items, panels, furniture, equipment, plant life, soil, snow, ice or debris that obstructs access or visibility.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
X	WALL CLADDING FLASHING AND TRIM Siding Style: Cement stucco Siding Material: Masonry
X	DOORS (Exterior) Exterior Entry Doors: Steel
X	WINDOWS and TRIM
2.3	DECKS, BALCONIES, STOOPS, STEPS, AREAWAYS, PORCHES, PATIO/ COVER AND APPLICABLE RAILINGS Appurtenance: Patio
X	VEGETATION, GRADING, DRAINAGE, DRIVEWAYS, PATIO FLOOR, WALKWAYS AND RETAINING WALLS (With respect to their effect on the condition of the building)  The air conditioner compressor cabinet bases are buried in mulch and should be elevated above the organic material approximately 2" to prevent premature corrosion of the cabinets and maintain efficient operation of the compressor units.

IN MD RR SN LI NI Inspection I tems

4321 New Home Road Page 7 of 26

#### IN MD RR SN LI NI

#### Inspection Items



2.4 Picture 1

X		2.5	EAVES, SOFFITS AND FASCIAS
X		<b>2.6</b>	Driveway Driveway: Asphalt

#### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The exterior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 8 of 26

#### 3. Interiors

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
X	CEILINGS Ceiling Materials: Drywall
🛚 🗎 🗎 🗎 3.1	WALLS Wall Material: Drywall
🛚 🗎 🗎 🗎 3.2	FLOORS Floor Covering(s): Carpet, Hardwood T&G, Linoleum
X	STEPS, STAIRWAYS, BALCONIES AND RAILINGS
X	COUNTERS AND A REPRESENTATIVE NUMBER OF CABINETS Cabinetry: Wood
	Countertop: Corian
⊠ □ □ □ □ 3.5	DOORS (REPRESENTATIVE NUMBER) Interior Doors: Hollow core, Raised panel, Wood
	The sump pump closet door is dragging severely on the carnet and should

The sump pump closet door is dragging severely on the carpet and should be undercut to prevent damage to the door or the hinges.



3.5 Picture 1

X		3.6	WINDOWS (REPRESENTATIVE NUMBER) Window Types: Thermal/Insulated, Double-hung, Casement
			Window Manufacturer: ANDERSEN

IN MD RR SN LI NI Inspection Items

4321 New Home Road Page 9 of 26

IN MD RR SN LI NI	Inspection Items
X	VENTING SYSTEMS (kitchens, baths and laundry)
IN MD RR SN LI NI	Inspection Items
IN=Inspected-Appears Function	onal, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection.

NI = Not Inspected

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go upported. The inspection did not involve moving furniture and

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 10 of 26

NI=Not Inspected

## 4. Structural Components

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
X	FOUNDATIONS, BASEMENTS
	Basement Foundation: Poured concrete
X	WALLS (Structural)
	Wall Structure: 2 X 4 Wood
$\Pi \Pi \Pi \Pi \Pi \Pi 4.2$	COLUMNS OR PIERS
	Columns or Piers: Not Visible
	The support columns were covered in building materials and were not visible. A limited inspection was performed on the columns.
$\Pi \Pi \Pi \Pi \blacksquare \Pi_{4.3}$	BEAMS/GIRDERS
· · ·	The support columns were covered in building materials and were not
	visible. A limited inspection was performed on the columns.
$\square$ $\square$ $\square$ $\square$ $\square$ $\square$ 4.4	FLOORS (Structural)
	Floor Structure: Engineered floor joists
	The refinished basement had building materials which blocked the view of the floor joists. This limited the inspection of the structural joists.
	CEILINGS (structural)
	Ceiling Structure: Not visible
	A limited inspection of the ceiling structure was performed because the ceiling joist were covered with building materials and blocked the view of
	the joists.
$ \nabla \Pi \Pi \Pi \Pi \Pi \Lambda A $	ROOF STRUCTURE AND ATTIC
	Roof Structure: Engineered wood trusses
	Roof-Type: Hip
	Method used to observe attic: From entry
	Attic info: Scuttle hole
IN MD RR SN LI NI	Inspection Items

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection,

4321 New Home Road Page 11 of 26

recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 12 of 26

## 5. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
X	PLUMBING DRAIN AND VENT PIPES Washer Drain Size: 2" Diameter
	Plumbing Waste: PVC
	Plumbing Vent: PVC
⊠	PLUMBING WATER SUPPLY AND DISTRIBUTION SYSTEMS AND FIXTURES Water Source: Public
	Water Filters: Whole house conditioner, None
	Plumbing Water Supply (into home): Copper
	Plumbing Water Distribution (inside home): Copper
X	PLUMBING WASTE/DRAIN PIPES
X	HOT WATER SYSTEMS, CONTROLS, CHIMNEYS, FLUES AND VENTS
X	WATER HEATER FUEL SHUTOFF The gas shutoff valve is located on the incoming steel gas line just to the left of the water heater.

IN MD RR SN LI NI Inspection Items

4321 New Home Road Page 13 of 26

#### IN MD RR SN LI NI

#### Inspection Items



5.4 Picture 1

WATER HEATER (describe)
The 75 gallon water heater uses natural gas as a fuel source, h

The 75 gallon water heater uses natural gas as a fuel source, has a thermostat on its exterior casing, has a drain valve at its base, and vents into a flue system.

X					5.6	MAIN	WATER	SHUT-OFF	DEVICE	(Describe	location)
---	--	--	--	--	-----	------	-------	----------	--------	-----------	-----------

The incoming water service shutoff valve in located on the copper pipe coming through the front basement wall in the 'mechanical room'.



5.6 Picture 1

IN	MD R	RR S	SN LI NI	Inspection Items
X			5.9	<b>SUMP PUMP</b> A limited inspection was performed on the sump pumps as they were not
X			5.8	MAIN FUEL SHUT OFF (Describe Location) There is no main fuel shutoff valve. All of the individual appliances have gas shutoff valves fairly close to the appliance.
X			<b> </b> 5.7	FUEL STORAGE AND DISTRIBUTION SYSTEMS (Interior fuel storage, piping, venting, supports, leaks)

4321 New Home Road Page 14 of 26

#### IN MD RR SN LI NI Inspection Items

tested.

#### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 15 of 26

## 6. Electrical System

The home inspector shall inspect: Service drop; Service entrance conductors, cables, and raceway; Service equipment and main disconnects; Service grounding; Interior components of service panels and sub panels; Conductors; Overcurrent protection devices; A representative number of installed lighting fixtures, switches, and receptacles; Ground fault circuit interrupters. A home inspector shall describe: Amperage and voltage rating of the service; Location of main disconnect(s); Presence of solid conductor aluminum branch circuit wiring; Presence or absence of smoke detectors; and wiring methods. The home inspector is not required to inspect: Remote control devices; Alarm systems and components; Low voltage wiring systems and components; Ancillary wiring systems and components, not a part of the primary electrical power distribution system; Measure amperage, voltage, or impedance; or Built-in vacuum equipment.

 $IN=Inspected-Appears\ Functional,\ MD=Material\ Defects,\ RR=Repair\ or\ Replace,\ SN=Service\ Needed,\ LI=Limited\ Inspection,\ NI=Not\ Inspected$ 

IN MD RR SN LI NI Inspection Items


SERVICE ENTRANCE CONDUCTORS
Electrical Service Conductors: Below ground

Electrical Service Conductors: Below ground

SERVICE AND GROUNDING EQUIPMENT
Main Panel Manufacturer: CUTLER HAMMER

MAIN OVERCURRENT PROTECTION, MAIN DISTRIBUTION PANELS
Main Panel Capacity: 200 AMP/240 VOLT
Main Panel Type: Circuit breakers

(1) The door bell transformer laying within the electric cabinet should be located outside the cabinet to reduce the possibility of an electric fire.



6.2 Picture 1

(2) The uppermost AFCI breaker with a broken test button should be replaced so an AFCI test of that circuit can be performed to reduce the risk of an electric fire.

IN MD RR SN LI NI Inspection I tems

4321 New Home Road Page 16 of 26

#### IN MD RR SN LI NI

Inspection Items




6.2 Picture 2

X	Ц	Ц	Ц	ЦL	<b>_</b> 6.3	Main Breaker Panel Location: Basement
		X			6.4	BRANCH CIRCUIT CONDUCTORS, OVERCURRENT DEVICES AND COMPATIBILITY OF THEIR AMPERAGE AND VOLTAGE Branch wire 15 and 20 AMP: Copper

Wiring Methods: Romex

The romex wire laying within the breaker panel and the other end of it (which may be in the furnace room) should be terminated properly to prevent the possibility of an electric shock.




6.4 Picture 1

x 🗌	6.5	CONNECTED DEVICES AND FIXTURES (Observed from a representative number operation of ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls)
x 🗌	6.6	POLARITY AND GROUNDING OF RECEPTACLES WITHIN 6 FEET OF INTERIOR PLUMBING FIXTURES, AND ALL RECEPTACLES IN

IN MD RR SN LI NI Inspection I tems

4321 New Home Road Page 17 of 26



IN MD RR SN LI NI Inspection I tems

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 18 of 26

## 7. Heating

The home inspector shall *inspect* permanently installed system components of the heating systems including: Heating equipment; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel burning appliances; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; Heating equipment, distribution type, fireplaces, solid fuel burning appliances and chimneys. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Inspect: The interior of flues or chimneys that are not readily accessible; Heat Exchangers; Humidifiers or dehumidifiers; Electronic air filters; or Solar space heating systems; Firescreens and doors; Seals and Gaskets; Automatic fuel feed devices; Mantles and fireplace surrounds; Combustion make-up air devices. or Determine: Heat supply adequacy or distribution balance.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected


IN MD RR SN LI NI Inspection Items ☑ ☐ ☐ ☐ ☐ 7.0 FURNACE - general Heat Type: Forced Air **Energy Source:** Gas Number of Heat Systems (excluding wood): Two Heat System Brand: CARRIER The home has two gas fueled furnaces. The right one is for the first floor, the left one for the second. These units operate separately off of independent thermostats located on their respective floors. The filters should be changed or checked after each cooling or heating season until a service record can be established. ☑ ☐ ☐ ☐ 7.1 NORMAL OPERATING CONTROLS ▼ □ □ □ □ 7.2 AUTOMATIC SAFETY CONTROLS ☐ ☐ ☐ ☐ ☐ 7.3 DISTRIBUTION SYSTEMS (including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units and convectors) **Ductwork:** Non-insulated Filter Type: Disposable, Cartridge Filter Size: 16x25 Filter 2 Size: 16x25 ☑ ☐ ☐ ☐ 7.4 FUEL SHUTOFF The gas shutoff valves are located on the incoming gas lines within the black pipe feeding each unit. If you smell gas all of these valves should be closed (turned 90 degrees) until a repairman can service and repair a leak.

IN MD RR SN LI NI Inspection I tems

4321 New Home Road Page 19 of 26

#### IN MD RR SN LI NI

#### Inspection Items





7.4 Picture 1

7.4 Picture 2

X			7.5	PRESENCE OF INSTALLED HEAT SOURCE IN EACH ROOM
X		]	7.6	CHIMNEYS, FLUES AND VENTS (for fireplaces, gas water heaters or heat systems)
	X	]	7.7	SOLID FUEL HEATING DEVICES (Fireplaces, Woodstove) Type of Fireplace(solid fuel): Insert
				Operable Fireplaces: One
				Number of Woodstoves: None
				The deteriorated fire brick plate in the back wall of the fireplace should be replaced to prevent a house fire from the fireplace.

#### IN MD RR SN LI NI Inspection I tems

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The heating system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 20 of 26

## 8. Central Air Conditioning

The home inspector shall: Open readily openable access panels; Inspect: central and through-wall equipment; Distribution systems; Describe: Energy source(s); Cooling systems. The home inspector shall operate the systems using normal operating controls. The home inspector is not required to: Operate cooling systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; or Inspect: Humidifiers; Electronic air filters; Window air conditioning units or Determine: the uniformity or adequacy of cooling supply to the various rooms.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN	MD	RR	SN I	LI NI	Inspection Items
X				8.	COOLING AND AIR HANDLER EQUIPMENT
X				<b>]</b>	1 NORMAL OPERATING CONTROLS
X				🛮 🖟 в.	2 PRESENCE OF INSTALLED COOLING IN EACH ROOM
X				<b>] [</b> ] 8.	3 DISTRIBUTION SYSTEMS (including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units and convectors)

#### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 21 of 26

## 9. Attic & Venting

The home inspector shall inspect: Insulation and vapor retarders in unfinished spaces; Ventilation of attics and foundation areas; Mechanical ventilation systems; Kitchen, bathroom, and laundry venting systems; and the operation of any readily accessible attic ventilation fan. The home inspector shall describe: Insulation and vapor barriers in unfinished spaces; and Absence of insulation in unfinished space at conditioned surfaces. The home inspector shall: Move insulation where readily visible evidence indicates the need to do so; and Move insulation where chimneys penetrate roofs, where plumbing drain/waste pipes penetrate floors, adjacent to earth filled stoops or porches, and at exterior doors. The home inspector is not required to report on: Concealed insulation and vapor retarders; or Venting equipment that is integral with household appliances.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
<b>X</b>	INSULATION and VAPOR RETARDERS IN ATTIC Attic Insulation: Loose fill, Cellulose
□     □     □     □     □     9.1	INSULATION and VAPOR RETARDERS IN UNFINISHED SPACE Vapor retarders are not visible as their view is blocked by building materials. Their inspection was limited.
9.2	INSULATION UNDER FLOOR SYSTEM Floor System Insulation: Not visible
	Floor insulation was not visible as its view was blocked by building materials. The floor insulation inspection was limited.
9.3	VENTILATION OF ATTIC Ventilation: Ridge vents, Soffit Vents
☑ □ □ □ □ 9.4	VENTING SYSTEMS (Kitchens, baths and laundry) Exhaust Fans: None Dryer Power Source: Gas Connection
	Dryer Vent: Flexible Metal

### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The insulation and ventilation of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Venting of exhaust fans or clothes dryer cannot be fully inspected and bends or obstructions can occur without being accessible or visible (behind wall and ceiling coverings). Only insulation that is visible was inspected. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 22 of 26

#### 10. Basement

The Home Inspector shall inspect structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely affect the health of the home inspector or other persons.

 $IN=Inspected-Appears\ Functional,\ MD=Material\ Defects,\ RR=Repair\ or\ Replace,\ SN=Service\ Needed,\ LI=Limited\ Inspection,\ NI=Not\ Inspected$ 

IN MD RR SN LI NI	Inspection Items
X   10.0	WALLS (Structural)
10.1	COLUMNS OR PIERS see 10.2
X             10.2	<b>REFINISHED BASEMENT</b> The refinished basement limited the inspection of all the components covered by building materials.

#### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 23 of 26

## 11. Built-In Kitchen Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
X         11.0	DISHWASHER Dishwasher Brand: GENERAL ELECTRIC
X           11.1	COOKTOP
X       11.2	OVENS Oven: GENERAL ELECTRIC
	Cooktop: GENERAL ELECTRIC
X           11.3	RANGE HOOD Exhaust/Range hood: GENERAL ELECTRIC
X           11.4	FOOD WASTE DI SPOSER Disposer Brand: GENERAL ELECTRIC
X           11.5	MICROWAVE COOKING EQUIPMENT Built in Microwave: GENERAL ELECTRIC

#### IN MD RR SN LI NI Inspection Items

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

4321 New Home Road Page 24 of 26

## 12. Garage

A home inspector shall inspect: Walls, ceiling, and floors; Garage door(s); Occupant door; Garage door operators (operate garage doors manually or by using permanently installed controls for any garage door operator); Report whether or not any garage door operator will automatically reverse or stop when meeting reasonable resistance during closing; Garage stairs; Garage electric; and One hour fire separation. The inspector is not required to inspect: paint, wallpaper, and other finish treatments; shelving, workbenches or any other accessories; Garage door operation by using the remote control transmitters.

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

IN MD RR SN LI NI	Inspection Items
X	GARAGE CEILINGS
X	GARAGE WALLS (INCLUDING FIREWALL SEPARATION)
12.2	GARAGE FLOOR Garage Floor: Concrete
12.3	GARAGE DOOR (S) Garage Door Type: Two automatic
	Garage Door Material: Insulated, Metal
X	OCCUPANT DOOR FROM GARAGE TO INSIDE HOME
12.5	GARAGE DOOR OPERATORS (Report whether or not doors will reverse when met with resistance) Auto-opener Manufacturer: LIFT-MASTER
	The garage doors reversed when met with moderate force and the floor sensors reversed the doors when the light beam was broken.
X	GARAGE ELECTRIC
12.7	GARAGE STAIRS

IN MD RR SN LI NI Inspection I tems

IN=Inspected-Appears Functional, MD=Material Defects, RR=Repair or Replace, SN=Service Needed, LI=Limited Inspection, NI=Not Inspected

The garage was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving shelving, storage items, work benches, equipment, tools, or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

Prepared Using HomeGauge http://www.homegauge.com SHGI (c) 2000-2008: Licensed To Maurer Inspections, LLC

4321 New Home Road Page 25 of 26



## Maurer Inspections, LLC

#### **Steve Maurer**

3633 Buttonwood Drive Doylestown, PA 18902 267-884-4047 NJ Lic#24G100097300



4321 New Home Road Page 26 of 26